Date

Monday, 12/05/2008 3:24:56 PM

User:

Linda Lacelle

Process Sheet

Customer

: CU-DAR001

Job Number **Estimate Number** : 39208

: 10335

P.O. Number

This Issue

: 12/05/2008 : NC

Prsht Rev. : // First Issue

Previous Run

: 38796

Checked & Approved By

Comment

Written By

: Est A 04.02.17

Type

S.O. No. :

New issue KJ/JLM

: SMALL /MED FAB

Drawing Name

: MIRROR ARM

: D2010104

Part Number

D2010 REV. C2

Drawing Number Project Number

: N/A : C2

Drawing Revision

Material

Due Date

: 19/05/2008

per attached emzi

Qty:

1 Um:

Each

Additional Product

Job Number:



Seq. #:

1.0

3.0

M304TR0500W935

Description:

304 RD Tube .500 x .035W

Comment: Qty.: 1.5750 f(s)/Unit Total:

1.5750 f(s) Material: 304/316 SS tubing 0.500" Dia. x 0,935" wall

(M304TR0500W035) BRAKE NC

NC BRAKE

GA manual fabri

Comment: BRAKE NC

Punch per Dwg. D2010-104 and Spec Control Dwg. D2727

Identify as D2010-104

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE

M 107518



Comment: SMALL & MEDIUM FAB RESOURCE 1

1- Bend as per Dwg D2010 using bending Jig D2010-104T2

2- Deburr

4.0 D2057 Plug



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Plug batch

5.0

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

1- flare before installing plug as per dwg D2010

2- Install D2057 plug as per Dwg D2010

Dart Aerospace Ltd

| W/O: | | WORK ORDER CHANGES | | | | | | | | |
|-----------|------|------------------------|----|------|-----|-------------------------------------|--------------------------|--|--|--|
| DATE | STEP | PROCEDURE CHANGE | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector | | | |
| C8.65.17_ | 1 | INSTEAD OF 0.035" WALL | | | | 08.05.12 08.042 | dut | | | |
| | | | | · | | | | | | |

| Part No: _ | PAR #: | Fault Category: | NCR: Yes No DQA: | Date: |
|------------|--------|-----------------|------------------|-----------|
| | | | QA: N/C Closed: | Date: |

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | | | | |
|------|------|----------------------------------|----------------------|------------------------------|----------------|------------|-----------|--------------------------|--|--|--|
| DATE | | Description of NC | | Corrective Action Section B | Verification | Approval | Ammousel | | | | |
| | STEP | Section A | Initial Chief Eng | Action Description Chief Eng | Sign & Date | Section C | Chief Eng | Approval QC Inspector | | | |
| | | | | 1 | | | | | | | |
| | | | | | | | , | "种" | | | |
| | | | | | | | · - ~ | | | | |
| | | | | ***** | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | - | | | | | | | | | | |
| | | | | | | <i>:</i> : | | | | | |
| | | | | | | | | | | | |
| | | | | | | 4 | | | | | |

NOTE: Date & initial all entries

Monday, 12/05/2008 3:24:56 PM Date: Linda Lacelle User: **Process Sheet** Customer: CU-DAR001 **Drawing Name: MIRROR ARM** Job Number: 39208 Part Number: D2010104 Job Number: Seq. #: **Machine Or Operation:** Description: INSPECT WORK TO CURRENT STEP 6.0 Comment: INSPECT WORK TO CURRENT STEP 7.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat Black Sandtex (Ref: 4.3.5.7) as per QSI 005 4.3 START TIME: **OVEN TEMPERATURE:** FINISH TIME: 8.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT 9.0 PACKAGING 1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

10.0

QC21

FINAL INSPECTION/W/O RELEASE


Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



| Dart Ae | rospace | Ltd | | | | • | | | | |
|---------|---------|--------------------------------|--|---------------|-----------|--------|----------|----------------|-------------------------------------|--------------------------|
| W/O: | | | ٧ | VORK ORDER CH | IANGES | | | | | |
| DATE | STEP | PROCEDURE CHANGE | | | | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | b. | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| Part No | : | PAR #: | _ Fault Ca | tegory: | NC | R: Yes | No DQ | A: | Date: | |
| | ÷ | | | | | QA: N | /C Close | d: | _ Date: _ | |
| NCR: | | W | ORK OR | DER NON-CONFO | DRMANCE | (NCR | () | | | |
| DATE | STEP | Description of NC Section A | escription of NC Section A Initial Chief Eng | | Section B | Sign & | | cation on C | Approval Chief Eng | Approval QC Inspector |
| | | | Chief Eng | Chief Eng | | Date | | | · | |
| | | | | | | | | | 34- | |
| | | | | | | 3 = | | | | |
| | 1 | | | | | | | | | |

NOTE: Date & initial all entries



L Lacelle

From:

Bill Beckett [bbeckett@dartaero.com]

Sent:

May 12, 2008 3:16 PM

To:

'L Lacelle'

Cc:

'Sian Willems'; 'Dan Stow'; 'Chris Provencal'; 'David Shepherd'; 'Mike Petsche'

Subject: FW: R44 Mirror arm D2010-104

Linda.

Please make one of these up ASAP. I would like to ship as a no-charge to Canadian tomorrow.

Thanks,

Bill

From: David Shepherd [mailto:dshepherd@dartaero.com]

Sent: May 12, 2008 2:28 PM
To: 'Chris Provencal'; 'Mike Petsche'

Cc: 'Peter Hum'; 'Bill Beckett'

Subject: RE: R44 Mirror arm D2010-104

This deviation is acceptable.

David

From: Chris Provencal [mailto:cprovencal@dartaero.com]

Sent: Monday, May 12, 2008 11:55 AM

To: 'Mike Petsche'; David Shepherd (David Shepherd)

Cc: Peter Hum; Bill Beckett

Subject: RE: R44 Mirror arm D2010-104

David,

If we make a tube with 0.049" wall, can we sign this off as a deviation on the w/o? That's the quickest way to get it out the door.

If this will be a permanent change we'll eventually need a new dwg and a new CHG #.

-Chris

From: Mike Petsche [mailto:mpetsche@dartaero.com]

Sent: May 12, 2008 9:36 AM

To: 'Bill Beckett'; 'Dan Stow'; 'Chris Provencal' **Cc:** 'L Lacelle'; 'David Shepherd'; 'Peter Hum' **Subject:** RE: R44 Mirror arm D2010-104

lassume someone's rasing a new NCR......We had one open from the last time this haapened but we never ended up getting broken part back. Pretty sure we ended up shutting it down.

It should be directed to Peter.

From: Bill Beckett [mailto:bbeckett@dartaero.com]

Sent: May 12, 2008 9:27 AM

To: 'Dan Stow'; 'Mike Petsche'; 'Chris Provencal'

Cc: 'L Lacelle'; 'David Shepherd'

Subject: RE: R44 Mirror arm D2010-104

Dan - Yup, let's send him a replacement mirror arm, but I don't want to send out something that has a good chance of failing.

Chris - I suggest we make an arm with 0.049" wall vs. the 0.035" called up on the drawing, and that we sign this off as a deviation. If this is acceptable, please advise Linda ASAP.

Mike - we need to come up with a permanent solution to this issue ASAP - I believe this will apply to the R22 and MD500 as well.

Bill

From: Dan Stow [mailto:dstow@dartaero.com]

Sent: May 12, 2008 8:05 AM **To:** Bill Beckett (Bill Beckett)

Subject: FW: R44 Mirror arm D2010-104

Importance: High

Bill,

I sent you this email last week. I am sending Russ to CHC today to pick up the skid and I need to know if you would like to send Claude a new R44 mirror arm and pick up the one that is cracked.

Dan Stow

Technical Support

Dart Aerospace

Tel: 613.632.5200 Cell:613.676.0992

dstow@dartaero.com

From: CBoule@canadianhelicopters.com [mailto:CBoule@canadianhelicopters.com]

Sent: May 8, 2008 10:04 AM

To: Dan Stow

Subject: RE: R44 Mirror arm D2010-104

Hi Dan

We have few that cracked.

I have in my hand one the cracked strut, can I shipped it to your attention, have your Engineer group to look at it for a fix.

Claude Boulé Chief Engineer, VFR, Qc/ On/ Nb. Tel: 450-452-3025 Fax: 450-452-2483 cboule@canadianhelicopters.com

"Dan Stow" <dstow@dartaero.com>

To <CBoule@canadianhelicopters.com>

CC

20/12/2007 04:15 PM

Subject RE: R44 Mirror arm D2010-104

Hi Claude,

I have heard about this problem once before and I thought that it might be an isolated incident... I guess not. I will bring this to the attention of the design team. If you could please supply me with the Batch # of the mirror assembly and a shipping address I will send out a new arm ASAP.

Thanks for the feedback.

Dan Stow Technical Support Dart Aerospace Tel: 613.632.5200

Cell:613.676.0992

dstow@dartaero.com

From: CBoule@canadianhelicopters.com [mailto:CBoule@canadianhelicopters.com]

Sent: December 20, 2007 3:53 PM

To: dstow@dartaero.com

Subject: R44 Mirror arm D2010-104

Hi

We have been replacing the D2010-104 due to crack at the mirror attachment.

It is a weak point of the design.

See attached pictures.

Were you aware about This defect?

Claude Boulé Tel: 450-452-3025 Fax: 450-452-2483

12/05/2008